



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246



646.4001
Job Sheet 189564



Part No: 646.4001

Job Qty: 1 ea

Part Name: AS350 Cable Cutter System



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 1/28/19

Job Tracking No:

Due Date: 3/25/19

Created By: Jesse White

Type: Stock

Description: SIOP

Note: DWG REV C1 IPP REV:A 12.10.23 NEW ISSUE DD VERF:JLM IPP REV:B 15.01.08 AS PER DWG REV.B DD VERF:JLM IPP REV:C 16.01.07 AS PER DWG REV.C DD VERF:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Lead Time
					Setup Hrs	Run Hrs	Workcenter / Supplier		
90	Start up Operation	1 Ea	3/25/19	3/25/19	0.00	0.00	Start Up Stores/Pkg-1		
110	Packaging	1 pcs	3/25/19	3/25/19	0.00	0.00	Packaging1-1		
120	QC	1 pcs	3/25/19	3/25/19	0.00	0.00	QC4		
130	Packaging	1 pcs	3/25/19	3/25/19	0.00	0.00	Packaging3-1		
135	DC	1 pcs	3/25/19	3/25/19	0.00	0.00	DC		
140	QC21-FG	1 Ea	3/25/19	3/25/19	0.00	0.00	QC21		

MAR 01 2019

Sign-off
MAR 13 2019

MAR 13 2019

MAR 13 2019

DAS

70

9-89

Part Op 130 - Identify and pack for shipping as per PPP 646.4001 Location: _____
Descriptions: 135 - Photocopy bluefile & type labels per PPP 646.4001

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
600.0129	VHB Tape	8 ft (8 ea)	90-Start up Operation	5019004
600.0990	Magnabond 6398 Part A Size 112 ml	1 Ea (1 ea)	90-Start up Operation	5136925
600.0991	Magnabond 6398 Part B Size 112 ml	1 Ea (1 ea)	90-Start up Operation	5136931
600.1012	Sealant PR1425B2 (#654 sem)	1 pcs (1 ea)	90-Start up Operation	5133790
600.1013	021200-3M Tape Primer 94 Primer 24216	5 Ea (5 ea)	90-Start up Operation	5136734
646.2910	Deflector	1 pcs (1 ea)	90-Start up Operation	5093821
646.3001	Lower Cable Cutter Assembly	1 Ea (1 ea)	90-Start up Operation	5159178
646.3110	Channel	1 Ea (1 ea)	90-Start up Operation	5136495
646.3210	Support	1 Ea (1 ea)	90-Start up Operation	5131207
646.3301	Upper Cutter Assembly	1 Ea (1 ea)	90-Start up Operation	5159082
646.3510	Strut	1 Ea (1 ea)	90-Start up Operation	5127240
646.3511	Strut	1 Ea (1 ea)	90-Start up Operation	5081639
646.3610	Filler	1 pcs (1 ea)	90-Start up Operation	5072241
646.3710	Doubler	1 pcs (1 ea)	90-Start up Operation	5059684
646.3711	Clip	1 pcs (1 ea)	90-Start up Operation	5063206
646.3712	Clip	1 pcs (1 ea)	90-Start up Operation	5128050
646.3713	Gusset	1 Ea (1 ea)	90-Start up Operation	5124418
646.3714	Gusset	1 pcs (1 ea)	90-Start up Operation	5038824
646.3715	Strut Doubler	2 pcs (2 ea)	90-Start up Operation	5139095
646.3716	Gauge Bracket	1 pcs (1 ea)	90-Start up Operation	5003780

Plex 1/28/19 1:11 PM dart.white.jesse

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date : _____	Sequence #: _____	QTY Affected : _____		MRB (QSI042) _____	
Description Work Order Deviation		 Container No: S161839 Part: 646.4001 Job No: 189564 Serial No/Batch: S161839 Revision: _____ Inspector: _____ Exp Date: 08/10/2019 Instructions: FAA STC SR02180LA 14/08/02, TS-STC SH09 -			
		Disposition			
		Completed By _____			
		Lead hand / Supervisor _____			
				QC / QA Coordinator _____	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details: _____					

646.3717	Doubler	1 pcs (1 ea)	90-Start up Operation	5082377	
646.3718	Custom Washer	2 pcs (2 ea)	90-Start up Operation	5145123	- à éditer
646.3719	Doubler	2 pcs (2 ea)	90-Start up Operation	5143744	
646.3810	Bracket	2 pcs (2 ea)	90-Start up Operation	5131074	
646.3811	Radius Block	1 pcs (1 ea)	90-Start up Operation	5070843	
646.3812	Gusset Bracket	2 Ea (2 ea)	90-Start up Operation	5150415	
646.3813	AS350 Strut Bracket	1 pcs (1 ea)	90-Start up Operation	5131319	
646.3910	Shim	4 pcs (4 ea)	90-Start up Operation	5128166	
646.3911	Shim	1 pcs (1 ea)	90-Start up Operation	5133609	
646.3912	Shim	4 pcs (4 ea)	90-Start up Operation	5124332	
646.3913	Shim	1 pcs (1 ea)	90-Start up Operation	5041498	
646.9410	Shim	1 pcs (1 ea)	90-Start up Operation	5056998	
647.0112	Strut Bracket	2 pcs (2 ea)	90-Start up Operation	5133711	
647.7703	Strut Assembly	2 pcs (2 ea)	90-Start up Operation	5143539	
650.9201	Eyelet Bracket Assembly	2 Ea (2 ea)	90-Start up Operation	5131245	
AN3-11A	Bolt	10 Ea (10 ea)	90-Start up Operation	5129948	
AN3-12A	Bolt	2 Ea (2 ea)	90-Start up Operation	5095479	
AN3-13A	Bolt	1 Ea (1 ea)	90-Start up Operation	5098032	
AN3-3A	Bolt	4 Ea (4 ea)	90-Start up Operation	5131193	
AN3-4A	Bolt	10 Ea (10 ea)	90-Start up Operation	511290144 5149128 X6	
AN3-5A	Bolt	2 Ea (2 ea)	90-Start up Operation	5149158	
AN3-6A	Bolt	2 Ea (2 ea)	90-Start up Operation	5103950	
AN316C4R	Nut, Jam	2 Ea (2 ea)	90-Start up Operation	5133132	
AN44-5A	Eyebolt	2 Ea (2 ea)	90-Start up Operation	5131212	
AN4C7A	Bolt	2 Ea (2 ea)	90-Start up Operation	5071343	
AN665-34R	Clevis	2 Ea (2 ea)	90-Start up Operation	5142147	
CCR264SS3-02	Cherry Rivet	36 Ea (36 ea)	90-Start up Operation	5133189	
CR3213-5-3	Cherry Rivet	14 Ea (14 ea)	90-Start up Operation	5130131	
MS20426AD5-7	Rivet	2 Ea (2 ea)	90-Start up Operation	FM133922-36	
MS20470AD5-5.5	Rivet	8 Ea (8 ea)	90-Start up Operation	FM134002	
MS20470AD5-6	Rivet	8 Ea (8 ea)	90-Start up Operation	5048892	
MS20470AD5-7	Rivet	3 Ea (3 ea)	90-Start up Operation	5123425	
MS21042L08	Nut	2 Ea (2 ea)	90-Start up Operation	5080644	
MS21042L3	Nut	63 Ea (63 ea)	90-Start up Operation	5130347	
MS21042L4	Nut	2 Ea (2 ea)	90-Start up Operation	5149814	
MS21047-3	Nut Plate	18 Ea (18 ea)	90-Start up Operation	5103943	
MS24693-C278	Screw	5 Ea (5 ea)	90-Start up Operation	5065341	
MS24694-S51	Screw	5 Ea (5 ea)	90-Start up Operation	5123459	
MS24694-S54	Screw	2 Ea (2 ea)	90-Start up Operation	51526167	
MS24694-S55	Screw	3 Ea (3 ea)	90-Start up Operation	5099526	
MS27039-08-13	Screw	2 Ea (2 ea)	90-Start up Operation	5123937	
MS27039-1-10	Screw	2 Ea (2 ea)	90-Start up Operation	5148665	
MS27039-1-12	Screw	6 Ea (6 ea)	90-Start up Operation	5124664	
MS27039-1-16	Screw	24 Ea (24 ea)	90-Start up Operation	5104364	
MS27039-1-19	Screw	22 Ea (22 ea)	90-Start up Operation	5102052	
MS27039-1-20	Screw	2 Ea (2 ea)	90-Start up Operation	5094554	
MS27039-1-21	Screw	4 Ea (4 ea)	90-Start up Operation	5104011	
NAS1149F0332P	Washer	144 Ea (144 ea)	90-Start up Operation	5134693	
NAS1149F0363P	Washer	2 Ea (2 ea)	90-Start up Operation	5075330	
NAS1149F0432P	Washer	4 Ea (4 ea)	90-Start up Operation	5152652	
NAS1149FN832P	Washer	4 Ea (4 ea)	90-Start up Operation	5143716	

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	600.0129	8	96	0
	600.0990	1	20	0
	600.0991	1	20	0
	600.1012	1	20	0
	600.1013	5	101	0
	646.2910	1	8	0
	646.3001	1	4	0
	646.3110	1	5	0
	646.3210	1	10	0

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date : _____	Sequence #: _____	QTY Affected : _____		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐ ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled		FAULT CATEGORY ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					

646.3301	1	4	0
646.3510	1	6	0
646.3511	1	25	0
646.3610	1	21	0
646.3710	1	34	0
646.3711	1	21	0
646.3712	1	24	0
646.3713	1	28	0
646.3714	1	27	0
646.3715	2	25	0
646.3716	1	20	0
646.3717	1	26	0
646.3718	2	32	0
646.3719	2	24	0
646.3810	2	10	0
646.3811	1	10	0
646.3812	2	4	0
646.3813	1	17	0
646.3910	4	69	0
646.3911	1	25	0
646.3912	4	41	0
646.3913	1	20	0
646.9410	1	82	0
647.0112	2	54	0
647.7703	2	18	0
650.9201	2	49	0
AN3-11A	10	107	0
AN3-12A	2	134	0
AN3-13A	1	73	0
AN3-3A	4	309	0
AN3-4A	10	105	0
AN3-5A	2	102	0
AN3-6A	2	127	0
AN316C4R	2	48	0
AN44-5A	2	43	0
AN4C7A	2	107	0
AN665-34R	2	28	0
CCR264SS3-02	36	509	0
CR3213-5-3	14	215	0
MS20426AD5-7	2	939	0
MS20470AD5-5.5	8	117	0
MS20470AD5-6	8	894	0
MS20470AD5-7	3	97	0
MS21042L08	2	1,237	0
MS21042L3	63	1,976	0
MS21042L4	2	1,579	0
MS21047-3	18	243	0
MS24693-C278	5	61	0
MS24694-S51	5	247	0
MS24694-S54	2	32	0
MS24694-S55	3	200	0
MS27039-08-13	2	489	0
MS27039-1-10	2	157	0
MS27039-1-12	6	108	0
MS27039-1-16	24	376	0
MS27039-1-19	22	263	0
MS27039-1-20	2	106	0
MS27039-1-21	4	46	0
NAS1149F0332P	144	1,965	0
NAS1149F0363P	2	474	0
NAS1149F0432P	4	810	0
NAS1149FN832P	4	3,186	0

Part Specifications

Specifications could not be found.

Plex 1/28/19 1:11 PM dart.white.jesse

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐		DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐																															
Date :		Sequence #:		QTY Affected :		MRB (QSI042)																													
Description Work Order Deviation				Disposition		Completed By																													
						Lead hand / Supervisor																													
						QC / QA Coordinator																													
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY <table border="0"><tr><td>☐ Pressure/Forced</td><td>☐ Contamination</td><td>☐ Power Loss/Surge</td><td>☐ Positioned Wrong</td></tr><tr><td>☐ Bending</td><td>☐ Misaligned/off center</td><td>☐ Folio/Program</td><td>☐ Outside Tolerance</td></tr><tr><td>☐ Crushing</td><td>☐ BOM/Route</td><td>☐ Grain Direction</td><td>☐ Drawing</td></tr><tr><td>☐ Cracks</td><td>☐ Broken/Damage/Defect</td><td>☐ Weld</td><td>☐ Finish</td></tr><tr><td>☐ Crimp/Kink/Ripple/Wave/Twist</td><td>☐ Incomplete/Unclear Instructions</td><td>☐ Wrong Stock Pulled</td><td>☐ Part Lost/Missing</td></tr><tr><td>☐ Marks/Chatter</td><td>☐ Drill Holes</td><td>☐ Out of Sequence</td><td>☐ Misread</td></tr><tr><td>☐ Mislabeled</td><td>☐ Fit/Function</td><td>☐ Off-set/Set-up</td><td></td></tr></table>						☐ Pressure/Forced	☐ Contamination	☐ Power Loss/Surge	☐ Positioned Wrong	☐ Bending	☐ Misaligned/off center	☐ Folio/Program	☐ Outside Tolerance	☐ Crushing	☐ BOM/Route	☐ Grain Direction	☐ Drawing	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Finish	☐ Crimp/Kink/Ripple/Wave/Twist	☐ Incomplete/Unclear Instructions	☐ Wrong Stock Pulled	☐ Part Lost/Missing	☐ Marks/Chatter	☐ Drill Holes	☐ Out of Sequence	☐ Misread	☐ Mislabeled	☐ Fit/Function	☐ Off-set/Set-up	
☐ Pressure/Forced	☐ Contamination	☐ Power Loss/Surge	☐ Positioned Wrong																																
☐ Bending	☐ Misaligned/off center	☐ Folio/Program	☐ Outside Tolerance																																
☐ Crushing	☐ BOM/Route	☐ Grain Direction	☐ Drawing																																
☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Finish																																
☐ Crimp/Kink/Ripple/Wave/Twist	☐ Incomplete/Unclear Instructions	☐ Wrong Stock Pulled	☐ Part Lost/Missing																																
☐ Marks/Chatter	☐ Drill Holes	☐ Out of Sequence	☐ Misread																																
☐ Mislabeled	☐ Fit/Function	☐ Off-set/Set-up																																	
Other/Details: _____ _____ _____																																			